

NOTICE OF DISCONTINUANCE OF SS FILTER CARTRIDGES

In 1984 Jordair and Bauer provided safety warning of the life limit for filter systems of 15 year from the date of installation. This applied to the gold coloured chambers using SS type cartridges as well as the blue TS types.

As these SS, NS & TS systems are all well past the safe operate dates Jordair has suspended the production of the SS type cartridges with immediate effective. Effective June 1st 2016 Jordair will discontinue production of the TS and NS type filter cartridges.

As these filter chambers are beyond the stated 15 year service life sourcing filter cartridges from other aftermarket companies is strongly advised against.

At Jordair our priority is the safety of our service groups and the operators of the breathing air compressor systems.

Anyone continuing to use these compressor systems with outdated filter chambers will incur both a personal safety risk as well as the possible legal liabilities involved in doing so.

If you are operating a compressor made by Bauer or with Bauer filter chambers please check the manufactured date on the chamber base tag to ensure the 15 year life cycle has not been exceeded. If over 15 years in service then the Bauer chambers are to be replaced.

Please note any replacement of filter chambers must be done with CRN certified chambers with the CRN for the jurisdiction of installation. This is a legal requirement in Canada.

Please keep the industry safe by ensuring that high pressure components do not exceed the manufactures recommended life span.

High pressure system contain huge kinetic energy so being safe should be everyone's number one priority.

JORDAIR - "RELIABILITY & SAFETY" - BAUER